

Title: Quality Control Inspector
Department: Quality Assurance
Shift Type: First Shift

Position Summary

Under the guidance of the Quality Assurance Manager, this position is responsible for performing inspections on machined components and assemblies.

Essential Functions

- First piece inspection
- In-process inspection
- Final inspection
- Be able to accurately document and record inspection results
- Perform incoming inspections of raw material
- Work with close tolerance parts
- Be able to identify non-conformances and generate reject reports
- Follow ISO quality management system requirements

Requirements

- Knowledge in use of measuring instruments: Calipers, Micrometers, Height gage, indicators, Bore Gages and other miscellaneous instruments.
- Able to read and interpret blue prints including GD&T
- High School education
- Basic computer skills
- Must be able to follow quality and safety standards
- Must be able to stand for long period of time
- Required to perform repetitive motions such as bending at the waist and squatting.